

**CALIFORNIA STATE RAILROAD MUSEUM**

**SACRAMENTO SOUTHERN RAILROAD**

**CIRCULAR –25**

**IMPAIRED CLEARANCE**

**APRIL 25, 2014**

Impaired Clearance exists with respect to walkways located between impact walls, on both sides of SSRR/UP Crossing at Control Point RV988.

The area of impairment is south of the SSRR diamond crossing at RV988.

**End of Circular—25**

Richard N. Noonan

Manager of Railroad Operations